BondRees

**Date:** 23/10/2024
**REF:** TSCM REPRESENTATION
**RE:** **TSCM-01235**

Bond Rees

TEL: 0800 002 9468

Email: bondrees@gmail.com

# INVESTIGATION REPORT

## Case Data:

**Case Details:**

**Objective TSCM Sweep of home address.**

**The client suspects a competitor has planted Audip and visual monitoring devices in his home address.**

**Client suspects ceiling.**

**The objective is to sweep the entire premises including the piter porch and phone taps outside the address.**

**Conduct harmonic signature sweeps of the area to establish whether any intrusive signals or receivers are near the address.**

**TSCM Equipment:**
**- MEFF M1 Pcro Spectrum Detector (0KHz- 20Ghz)**
**- T3 Standby Device Probe**
**- T4 Camera Lens probe**
**- IProtect 1216i Near Field Frequency Detector (Directional 50Mhz - 12Ghz)**
**- MWA -6 Directional Antenna**
**- MWA - 12 Directional Antenna**
**- Hikmicro Pocket 2 - Thermal Imagery Camera**

# REPORT

## AREA 1 ENTRANCE HALL




ALL IMAGES ARE DATED & TIME STAMPED

**Room Description:**
Small flat entrance hallway with fuse board fitted to a wall. Solid concrete & artex ceilings with concrete flooring in neighbour's flat. No disturbance to the ceiling. Floors assessed with no concerns raised.

**Sweeps included**

- Full physical search including lights, light switches, and fuse board.
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices
- Sweeps for receiving devices

BondRees

- Transmission assessments for the area.

As with any property, there is an abundance of transmissions ranging from Mobile, GSM, 3G 4G, Wifi, and data packets via satellite. There are also non-domestic frequencies such as FM, AM, CB and radio broadcasts.

## AREA 2 ADJOINING HALLWAY



ALL IMAGES ARE DATED & TIME STAMPED

**Room Description:**

Internal hallway with solid concrete & artex ceilings with concrete flooring in neighbour's flat. No disturbance to the ceiling. Floors assessed with no concerns raised.

Sweeps included

- Full physical search including lights, light switches
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices
- Sweeps for receiving devices

## AREA 3 LIVING ROOM



ALL IMAGES ARE DATED & TIME STAMPED

Again, as above identical sweep and analysis of the room.

Living area with scattered electronics TV Radio, Laptop and other electronic devices.

All devices have been individually assessed and cleared of spyware and malicious hardware.

Solid concrete & artex ceilings with concrete flooring in neighbour's flat. No disturbance to the ceiling. Floors assessed with no concerns raised.

**Sweeps included**

- Full physical search including lights, light switches
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices
- Sweeps for receiving devices

BondRees

- Transmission assessments for the area.

As with any property, there is an abundance of transmissions ranging from Mobile, GSM, 3G 4G, Wifi, and data packets via satellite. There are also non-domestic frequencies such as FM, AM, CB and radio broadcasts.

**AREA 4 BEDROOM**



ALL IMAGES ARE DATED & TIME STAMPED

**Room Description:**

Bedroom with a double bed, cupboard and bedside table. No damage or disturbance to walls or ceiling. Noted an emergency call device emitting a signal which was found to operate and contact an emergency call centre.

Sweeps included

- Full physical search including lights, light switches
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices
- Sweeps for receiving devices

**AREA 5 BATHROOM**

ALL IMAGES ARE DATED & TIME STAMPED

**Room Description:**

Bathroom with expected-to-see facilities. No disturbance to ceilings or walls.

Sweeps included

- Full physical search including lights, light switches,
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices
- Sweeps for receiving devices

**AREA 5 UTILITY AREA**



ALL IMAGES ARE DATED & TIME STAMPED

Room description: The boiler room is also used for storage. No disturbance to walls or ceilings.

Sweeps included

- Full physical search including lights, light switches, and fuse board.
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices
- Sweeps for receiving devices

**AREA 6 KITCHEN**



**Room Description:** Kitchen with expected-to-see furnishings. No damage to walls or ceilings. The client explains he hears a beeping noise when closing and opening the door. We were able to explain the beeping. This is an alarm/reminder to shut the fire door.

We note there is a smoke detector fitted near the door.

Sweeps included

- Full physical search including lights, light switches, and fuse board.
- Heat Signature sweep
- Harmonics & frequency ping assessments
- Sweeps of transmitting and broadcasting devices

BondRees

- Sweeps for receiving devices

## Summary:

A sweep of the property was conducted to confirm there are no recording devices present in the client's property. It has been explained to the client that due to the presence of concrete flooring, it is highly unlikely his neighbours will have installed a listening device within it. Listening devices require a microphone which will struggle to operate through reinforced floors. Video recording devices require a camera lens to operate which deems this method ineffective due to the absence of any lenses. It has also been explained to the client that when using his own RF detector he may be receiving signals from his neighbour's property, other neighbours' properties and even from his own devices (phone). A brief tutorial was provided to the client on how best to operate his device if he has any future concerns.

**This is a representation of a TSCM report. We have taken extracts from 5 reports and intermixed the data into one report with slight changes to ensure client privacy. Images are from an agreed source and have been blurred for privacy.**

**END REPORT…**

Yours sincerely

Paul Evans

Paul Evans

Bond Rees